







I59 - BIRMINGHAM - ALABAMA
PRECAST YARD
LAYOUT












8. LIFT SEGMENT N+1 AND APPLY EPOXY.




9. CONNECT SEGMENT N+1 TO SEGMENT N AND INSTALL TEMPORARY PT BARS (JACKS NOT IN CONTACT).




10. LOAD JACK TO SEGMENT N+1 BOTTOM SLAB AT DEFINED LOADING - PROVIDED FOR EACH CASES(*).




11. DISCONNECT SEGMENT LIFTING BEAM.
12. REPEAT 8 TO 11 FOR REMAINING SEGMENTS.






13. COMPLETION OF THE SPAN.



14. CAST WET JOINT BETWEEN PS AND S1 & Sz (LAST SEGMENT).





		Feb-18	Mar-18	Apr-18	May-18	Jun-18	Jul-18	Aug-18	Sep-18	Oct-18	Nov-18	Dec-18	Jan-19	Feb-19	Mar-19	Apr-19	May-19	Jun-19	Jul-19	Aug-19	Sep-19	Oct-19	T-DAYS
	CASTING OF SEGMENTS																						534
	DEMO WORK																						41
	ERECTION																						217

