



- Model x +
- Engineer's Notebook
 - INSPECTION
 - DEPRESSION NOTE #1
 - SPALL NOTE #1
 - CRACK NOTE #1
 - SPALL NOTE #2
 - CONTRACTOR
 - Folder 3

Ivan.Liu Sunday, February 4, 2018



Ivan.Liu Sunday, February 4, 2018
SPALL MADE ON 02/04/2018
USE REPAIR PROCEDURE SikaRepair 222
(SEE PDF BELOW)



DOCUMENT REPAIR PROCEDURE IN WORD DOC BELOW:

